


# OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>811 10TH ST</b>		City: <b>OREGON CITY</b>	
USGS Quad Name: <b>Oregon City</b>		GPS Latitude: <b>45 21 27 N</b>	Longitude: <b>122 36 02 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>31</b> Block: <b>115</b>	Lot: <b>3, 2x, 4x, 5x</b> Map #: <b>22E31AA</b> Tax Lot #: <b>7100</b>
Date of Construction: <b>1963</b>	Historic Name:		Historic Use or Function: <b>Domestic - single dwelling</b>
Grouping or Cluster Name: <b>NA</b>	*Current Name or Use: <b>Domestic - single dwelling</b>		Associated Archaeological Site: <b>Unknown</b>
Architectural Classification(s): <b>Ranch</b>		Plan Type/Shape: <b>Rectangle</b>	Number of Stories: <b>1.0</b>
Foundation Material: <b>Concrete</b>		Structural Framing: <b>Unknown</b>	Moved? <b>No</b>
Roof Type/Material: <b>Gable / Composition shingle</b>		Window Type/Material: <b>Aluminum sliders</b>	
Exterior Surface Materials Primary: <b>Composition shingle</b>		Secondary: <b>Cast stone</b>	Decorative:
Exterior Alterations or Additions/Approximate Date: <b>Siding has been altered.</b>			
Number and Type of Associated Resources:			
Integrity: <b>Excellent</b> Condition: <b>Good</b>		Local Ranking:	National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input checked="" type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This one story minimal tract house has a rectangular and sits on a poured concrete foundation. The cross gable roof is covered with composition shingles and is pierced by a chimney. The house is covered with lap siding with a water table of broken-face brick. Windows are primarily aluminum sliders. A double car garage dominates the front (south) façade.			
Statement of Significance:			

Researcher/Organization: <b>Heather Goodson / HPNW</b>		Date Recorded: <b>4/6/2002</b>
<b>Survey Form Page 1</b>	Address: <b>811 10TH ST</b>	Local Designation # <b>SHPO #</b>