

CITY OF OREGON CITY

Historic Review Board

221 MOLALA AVENUE, SUITE 200 OREGON CITY, OREGON 97045 TEL (503) 722-3789 FAX (503) 722-3880

Historic Preservation Renovation Grant Application

Please Print Clearly

Grant Application File # (staff to fill out)
Date: 4-16-2015 Tax Assessor Map and Parcel Number: 22E 31 AD 12000
Applicant Name: MARK MASIL Address: 514 TEFFER SON ST
Site Address: 514 JEFFERSON ST Historic Name: HATTIE STORY HOW
Phone Number: 503-347-3220 E-mail address: MWMASK @ 6MAIL
Historic Date (if known): Architectural Style: Gonne
Previous Grant Approval File #'sTotal Amount
How did you hear about the program?: WORD OF MOUTH
Treatment (circle one): Preservation Rehabilitation Restoration Reconstruction
(From the Secretary of the Interior's Standards for the Treatment of Historic Properties).
PRESERVATION focuses on the maintenance and repair of existing historic materials and retention of a property's form as it has evolved over time. (Protection and Stabilization have now been consolidated under this treatment.)
REHABILITATION acknowledges the need to alter or add to a historic property to meet continuing or changing uses while retaining the property's historic character.
RESTORATION depicts a property at a particular period of time in its history, while removing evidence of other periods.
RECONSTRUCTION re-creates vanished or non-surviving portions of a property for interpretive purposes.

Historic Review Board Planning Division Tel: 503-722-3789 Fax: 503-722-3880

Project Description: Briefly explain the proposed work and the materials to be used. If you are planning to paint your historic building, please attach a paint sample for approval. NOTE: SOME ALTERATIONS MAY REQUIRE HISTORIC REVIEW AND/OR BUILDING PERMITS. Please Contact Staff to determine if your project requires a building permit. (sash repair generally does not.)
REPAIR SIX WINDOWS - SASHES
AND EXTERIOR SILLS HAVE VARYING
LEVELS OF DRY-ROT AND SOME DO
NOT OPEN DUE TO THE SASHES BEING
BROKEN OR STICKING DUE TO TOO MUCH PAINT BUILDUP.
Historic Significance: Describe how the project will enhance the historical nature of, or preserve, renovate or rebuild, the historical aspects of the structure.
PRESERVING THE ORIGINAL WOOD & TO
MAKE THE HISTORICAL WINDOWS FUNCTIONAL
AGAIN. WHILE MAINTAINING THE ORIGINAL
LOOK OF THE PROPERTY.

	mentation: Indic c photographs, etc						iginal
NoT	LOOKINO		ALTER	THE	exten	101	
	MEED	TO	PRES	ERVE	ORIGI FAIL	NAC	
(1 00M)	Smoon, M	B	EFORE	THEY	FAU	AAR	T.
	N. C.						
	bmit a "before" ph e project. Digita l						
Paint: 10 gallons (tach the contracto @ \$25/each = \$250 nited to those perf); Siding	(drop lap): 6	00 feet, 1" x			
Materials and Lab	oor		Cost Estima	ate:	2660		
			Approx	imate Proje	ect Total:		

Total grant amount requested:___

roject scheduling.
Beginning Date: 6/1/2015 Completion Date: 9/1/2015
Since funding is limited, you must contact the Historic Review Board if you cannot start your project within 90 days of the scheduled beginning date to apply for a beginning time extension. Projects must be completed within 180 days of when the grant is awarded.
If you are approved for a Preservation Grant, you must contact the Board when you actually begin

If you are approved for a Preservation Grant, you must contact the Board when you actually begin the proposed work, and when you finish the project. Preservation Staff will inspect the work when the project is completed.

I have read the Secretary of the Interior's Standards for the Treatment of Historic Properties and the Oregon City Design Guidelines for Exterior Alterations and agree to do the project as submitted and approved within six months of the application. I will notify the Board when I begin the project and when the project is completed.

This grant program has been funded with the assistance of a matching grant-in-aid from the Oregon State Historic Preservation Office and the National Park Service. Regulations of the U.S. Department of the Interior strictly prohibit unlawful discrimination on the basis of race, color, national origin, age or handicap. Any person who believes he or she has been discriminated against in any program, activity, or facility operated by a recipient of Federal assistance should write to: Office of Equal Opportunity, National Park Service, 1849 C Street, NW, Washington, D.C. 20240.

Project Schoduling



Window # 5 is smaller. The other five windows are all same size.

I.					
Project Address:					
Window # keyed to site map	Window Location	: Upstair	s bea	hoon	^
Window # keyed to site map CONDITON		: Upstair Excellent	5 bea	√oo ∿ Fair	Poor
Window # keyed to site map CONDITON 1. Overall Condition Of The Window		9/3/04/			
Window # keyed to site map CONDITON 1. Overall Condition Of The Window 2. Condition Of The Paint	low	9/3/04/			
Window # keyed to site map CONDITON 1. Overall Condition Of The Window	low	9/3/04/			Poor X X
Window # keyed to site map CONDITON 1. Overall Condition Of The Window 2. Condition Of The Paint	low	9/3/04/			Poor X X X X
Window # keyed to site map CONDITON 1. Overall Condition Of The Wind 2. Condition Of The Paint 3. Condition Of The Frame And S	low	9/3/04/			Poor X X X X
Window # keyed to site map CONDITON 1. Overall Condition Of The Wind 2. Condition Of The Paint 3. Condition Of The Frame And State of the Sash	low	9/3/04/			Poor X X X X
Window # keyed to site map CONDITON 1. Overall Condition Of The Wind 2. Condition Of The Paint 3. Condition Of The Frame And Si 4. Condition Of The Sash 5. Condition of The Rails 6. Condition of The Stiles 7. Condition of The Muntins	low	9/3/04/			Poor X X X X
Window # keyed to site map CONDITON 1. Overall Condition Of The Wind 2. Condition Of The Paint 3. Condition Of The Frame And S 4. Condition Of The Sash 5. Condition of The Rails 6. Condition of The Stiles	low	9/3/04/		Fair	Poor X X
Window # keyed to site map CONDITON 1. Overall Condition Of The Wind 2. Condition Of The Paint 3. Condition Of The Frame And Si 4. Condition Of The Sash 5. Condition of The Rails 6. Condition of The Stiles 7. Condition of The Muntins	low	9/3/04/			Poor X X X X

WINDOW#1 EXTERIOR

1. Photo Description



WINDOW # 1

2. Photo Description:




Historic Review Board Planning Division Tel: 503-657-0891 Fax: 503-657-7892

PO Box 3040 Oregon City, OR 97045

			W 11 5	42 1000 300	
Project Address:					
Window # Z keyed to s	ite Window Location	: upstairs	bed	Pow	
тар					
CONDITON		77 77 -			
		Excellent	Good	Fair	Poor
1. Overall Condition Of The V	Vindow	Excellent	Good	Fair	X
2. Condition Of The Paint		Excellent	Good	Fair	X
2. Condition Of The Paint3. Condition Of The Frame Ar		Excellent	Good	Fair	X
2. Condition Of The Paint3. Condition Of The Frame Ar4. Condition Of The Sash		Excellent	Good	Fair	X × ×
 Condition Of The Paint Condition Of The Frame Ar Condition Of The Sash Condition of The Rails 		Excellent	Good	Fair	X × ×
 Condition Of The Paint Condition Of The Frame Ar Condition Of The Sash Condition of The Rails Condition of The Stiles 		Excellent	Good	Fair	X X X X
 Condition Of The Paint Condition Of The Frame Ar Condition Of The Sash Condition of The Rails Condition of The Stiles Condition of The Muntins 		Excellent	Good		X × ×
 Condition Of The Paint Condition Of The Frame Ar Condition Of The Sash Condition of The Rails Condition of The Stiles 		Excellent	Good	Fair	X × × × ×

WINDOW # 2 EXTERIOR

1. Photo Description



WINDOW #2

2. Photo Description:



Historic Review Board Planning Division Tel: 503-657-0891 Fax: 503-657-7892

Project Address:		39 10 19 11			
Window # 3 keyed to site	Window Location:	dance	2- 1	20100	200
тар		downst	air)	JEW DI	JWC
CONDITON		Excellent	Good	Fair	Poor
1. Overall Condition Of The Windo	ow				X
2. Condition Of The Paint					X
3. Condition Of The Frame And Sil	ll				X
4. Condition Of The Sash					X
5. Condition of The Rails					×
6. Condition of The Stiles					X X X X
7. Condition of The Muntins		70		- 5	
8. Condition of Hardware				义	
9. Glazing Problems					×
10. Other:					

WINDOW#3 EXTERIOR

1. Photo Description



WINDOW #3

2. Photo Description:




Historic Review Board Planning Division Tel: 503-657-0891 Fax: 503-657-7892

PO Box 3040 Oregon City, OR 97045

Project Address:					<u> </u>
YA7: 3 II 7 7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Window Location:	1 1			
map 4 Reyed to site	Transcon Eccations	downsta	n's be	droor	~
CONDITON		Excellent	Good	Fair	Poor
1. Overall Condition Of The Wind	low				X
2. Condition Of The Paint					X
3. Condition Of The Frame And Si	ill	-			×
4. Condition Of The Sash					
5. Condition of The Rails				100	×
6. Condition of The Stiles					X
7. Condition of The Muntins					×
8. Condition of Hardware				X	
9. Glazing Problems					×
10. Other:					

WINDOW#4 EXTERIOR

1. Photo Description



WIN DOW # 4

2. Photo Description:




Historic Review Board Planning Division Tel: 503-657-0891 Fax: 503-657-7892

Project Address:				
Window # 5 keyed to site Window Location map	: Stairw	eil		
CONDITON	Excellent	Good	Fair	Poor
1. Overall Condition Of The Window				×
2. Condition Of The Paint				X
3. Condition Of The Frame And Sill				×
4. Condition Of The Sash				×
5. Condition of The Rails				X
6. Condition of The Stiles				X
7. Condition of The Muntins				×
8. Condition of Hardware			X	
9. Glazing Problems				X
10. Other:				

WINDOW #5

1. Photo Description



WINDOW #5

2. Photo Description:



Historic Review Board Planning Division Tel: 503-657-0891 Fax: 503-657-7892

Project Address:					
Window # & keyed to site Window	Location:	diaina	0000	^	
map		dining	100.0		
CONDITON	Ex	cellent	Good	Fair	Poor
1. Overall Condition Of The Window					X
2. Condition Of The Paint					×
3. Condition Of The Frame And Sill					×
4. Condition Of The Sash					X
5. Condition of The Rails					
6. Condition of The Stiles					×
7. Condition of The Muntins					×
8. Condition of Hardware				X	
9. Glazing Problems					
10. Other:		1			\times

WINDOW # 6 EXTERIOR

1. Photo Description



WINDOW # 6 INTERIOR

2. Photo Description:



Historic Review Board Planning Division Tel: 503-657-0891 Fax: 503-657-7892



Mark Mask < mwmask@gmail.com>

Window Restoration Outline

Jeffrey Franz <jeffreyfranzrepairs@gmail.com> To: mwmask@gmail.com

Sun, Mar 22, 2015 at 11:23 PM

Mark Mask 514 Jefferson St Oregon City OR 97045 503-347-3220

Price outline for window restoration

The restoration of lower sash of two-sash windows involves removing the lower sashes for examination to see if they can be restored and paint-stripped at a commercial paint stripper. If the wood is decayed beyond a restorable amount, new Fir sashes will be ordered from a local manufacturer, who uses the same sticking profile and dimensions as the original sashes.

If restored, the old putty will be removed and weak points will receive a special repair epoxy made for wood. Linseed oil, new putty and primer will be applied. If the owner provides paint, two or three coats of paint applied. The restored sash will be installed so that it operates smoothly, with v-flex weather strips installed on all four surfaces to eliminate air leaks.

If the owner chooses a varnish finish, the price will be the same as paint, and will include three coats interior, and four coats on the exterior. If owner does not have paint, the price of paint will be added to the price of the job.

The price for this work is.......\$300 for each lower window sash, new or restored.

The price for the one casement window on the stairway landing is \$200.

Possible custom glass panes will be discussed prior to any work, such as tempered, double-strength, or double-pane, and a price in addition to the above price arrived at.

Other restorations that were reviewed for possible work includes repair work to the sills which have suffered from grain cracks and weathering. The work will involve paint stripping, linseed oil, primer and caulk. The price of these repairs are \$80 to \$100 each sill, depending on the need to use the epoxy.

The restoration of the exterior jambs includes removing loose paint up to the point that the upper sash is fixed. This is to be done to prevent paint from chipping off in the future. The price for this work is \$40 to \$60 for each window opening. Contractor will consider combining this work with the sill restoration so as to arrive at a more economical price.

Homeowner	Date
Contractor	Date

Jeffrey G. Franz Sole Proprietor, CCB# 160533 1230 SE Morrison, Ste 408 Portland OR 97214



Mark Mask <mwmask@gmail.com>

Window Restoration Outline

Jeffrey Franz < jeffreyfranzrepairs@gmail.com> To: Mark Mask <mwmask@gmail.com>

Wed, Apr 15, 2015 at 11:03 PM

Mark Mask

514 Jefferson St Oregon City OR 97045 503-347-3220

Contract for Window Restoration as described on March 22, 2015

\$60 for each of six pairs of window jambs..... \$100 each for the repair of six window sills.....(\$600) \$200 for restoration of one small casement window in the stairwell....(\$200) \$300 for each of the five lower sashes selected by owner...(\$1,500) Total for repairs listed.....(\$2,660)(\$360)

Sole Proprietor, CCB# 160533 503-234-9641 1230 SE Morrison, Ste.408 Portland OR 97214 Jeffrey G. Franz

$The SASHMAN_{4027\ N\ E\ 42^{nd}\ Avenue\ Portland, OR\ 97213-1011\ 503-281-1010\ Avenue\ Portland}$

3416 CCB#203774

Following is a list of services provided when restoring a set of DH wood windows:

Removal of paint from the interior and exterior faces of the vertical and horizontal rails of the upper and lower sashes. If the interior is stained and varnished the paint will only be removed from the exterior surfaces leaving the interior finish intact.

Removal of paint from the track in the frames that the sashes slide on.

Lubrication of pulleys.

If metal weather-stripping exists the surfaces will be cleaned up and polished to give the sashes an easy slide.

Replace all sash cord with #7 cotton sash cord with nylon fiber running through the interior of the cord. This cord has an 800 pound test weight.

Sashes will be reinstalled on the same day that they are removed. No windows will be left open at the end of a work day.

Windows will be as close to original working condition as possible.

The cost for service on a window up to 5ft. high and 4ft. wide is as follows:

\$300.00 per window (two or more windows)

\$325.00 per window (if only restoring one window)

\$325.00 per window (if window is over a sink)

\$350.00 per window (if window is over a sink and is the only window being restored)

Windows over 5ft high or 4 ft. wide go up increments of \$25.00 depending on size. Additional Services included upon request:

1. Re-glazing and/or glass repair (only on windows that are being restored) is

\$7.50 per line plus the glass price. (Because the old wavy glass of so very fragile, we do not guarantee the glass if we have to remove any of the old glazing in order to re-glaze the sash properly. We are extremely cautious and or breakage rate is very low (less that 1%) We feel that is necessary to make you aware that there is a chance that this glass could fracture and that the client is responsible for the replacement cost.

2. Installation of new latches or locks.

If new latches or locks are desired it is the clients responsibility to pick out and purchase them before the job date. The cost to install new hardware is \$5.00 per sash-lock set and \$2.50 per sash-lift.

SERVICES NOT INCLUDED

Repainting

Washing Windows

Sill and frame repair.

*This estimate does not include any additional labor not mentioned in the above list of services or any unforeseen materials cost that may occur such as replacement weights, parting bead, wood stop or unrestorable sashes. No additional labor will be done or materials purchased without first consulting the client.

Projects scheduled for less than one week: Payment for work is due upon completion of project.

Projects scheduled for more than one week: Payment is due on the last day of each work week for work completed up to that point in time.

ESTIMATE PRICES ARE VALID THROUGH DECEMBER 2015

The same attention is given to the restoration of historic casement windows, pocket windows, transom windows hurricane windows, and slider windows.

RENOVATION GRANT CHECK LIST

(to be completed by staff)

	Application submitted (Date:)
·	W9 Submitted
ÿ 	Historic eligibility verified
(Ownership verified
	HRB review of request (date):
	Letter sent to the applicant of HRB action
	Approved
	Denied (reason for denial):Additional information requested:
	Work begun (date):
	Work Completed (date):
	Follow-up inspection. Date:
Total cost of	project: \$
Grant awarde	ed: \$
Amount due	owner: \$Check sent (Date:
(Not to excee	d either the project costs or the grant awarded, whichever is the lesser)