



## **Park Operations Facility**

### **Current Conditions Photos**

City Commission Work Session 4/11/2017



Figure 1. Park Operations Building which is currently unusable due to structural failures.



Figure 2. Non-ADA compliant Cemetery public restroom building



Figure 3. Restroom interior wall moisture




Figure 4. Restroom interior



Figure 5. Rented pod unit for park operations staff



Figure 6. Locker area in rented pod space



Figure 7. locker area in rented pod space



Figure 8. Adjacent metal shop building, not included in project