

Membrane Structure Violations

	CASE #	REMAINING STRUCTURES	YEAR APPEARS IN AERIAL PHOTOS	EST. SETBACK	EST. HEIGHT	EST. SQ. FT.	BUILDING PERMIT?	SETBACKS MET?	SEPERATION FROM HOME MET?	BUILDING MATERIAL	LOT COVERAGE MET?
1	CE19129	19230 Pine Place	2005	0	14	300	N	No	No	Metal	Yes
2	CE19128	19385 Hazel Grove Dr.	2002	0	14	400	N	No	No	Metal	Yes
3	CE19130	19379 Vincent Dr.	2007	0	10	180	N	No	No	Metal	Yes
4	CE19252	19437 Westling Dr.	2012	0	10	152	N	No	No	Metal	Yes
5	CE19153	19329 Auburn Dr.	2011	0	15	429	N	No	No	Metal	Yes
6	CE19155	18835 Lafayette Ave.	2011	1-2 ft?	10	189	N	No	Yes	Metal	Yes
7	CE19154	18765 Lassen Ct.	2011	0	8	360	N	No	No	Metal	Yes
8	CE19163	11721 Partlow Rd.	2000 or earlier	10 to 15	14	319	N	Yes	Yes	Metal	Yes
9	CE19161	18844 Hein St.	2005	0	10	180	N	No	No	Metal	Yes
10	CE19159	12050 Four Oaks St.	2007	0	16	420	N	No	No	Metal	Yes
11	CE19160	12052 Four Oaks St.	1999 or earlier	0	18	490	N	No	No	Metal	Yes
12	CE19156	13168 Autumn Ln	2001 or earlier	1 to 2 at corner	14	500	N	No	No	Metal	Yes
13	CE19157	19332 Whitney Ln.	2012 (leaf on)	0	16	190	N	No	Yes	Metal	Yes
14	CE18969	19277 Minuet Ct.	2004	0	14	240	N	Unknown	Unknown	Metal	Yes
15	CE19017	19579 Kari Ann Ct.	not present in 2015	0	14	280	N	No	No	Metal	Yes
16	CE19175	18936 Shenandoah Dr.	not present in 2015	0	10	200	N	No	No	Metal	Yes
17	CE19158	18840 Shenandoah Dr.	2003	maybe 1ft	10	330	N	No	No	Metal	Yes
18	CE19131	11315 Brandow St.	not present in 2015	0	12	153	N	No	No	Metal	Yes